


AD-A070 835

O'BRIEN AND GERE ENGINEERS INC PHILADELPHIA PA JUSTIN--ETC F/G 13/2  
NATIONAL DAM INSPECTION PROGRAM. PENN LAKE DAM (NDI ID NUMBER P--ETC(U)  
MAR 79 DACW31-79-C-0010

UNCLASSIFIED


NL

1 OF 1  
AD  
A070835



ADA070835

**LEVEL**  
DELAWARE RIVER BASIN  
WRIGHT CREEK, LUZERNE COUNTY



PENNSYLVANIA  
**PENN LAKE DAM**

NDI-PA 00542  
PA DER 40-28


PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM



Distribution Unlimited  
Approved for Public Release  
Contract No. DACW31-79-C-0010



Prepared By  
**O'BRIEN & GERE**  
Justin & Courtney Division  
PHILADELPHIA, PENNSYLVANIA  
19103



FOR  
DEPARTMENT OF THE ARMY  
BALTIMORE DISTRICT CORPS OF ENGINEERS  
BALTIMORE, MARYLAND  
21203

DDC FILE COPY

MARCH 1979

7 05 101

Accession For	
NTIS GRA&I	<input checked="" type="checkbox"/>
DDC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
By _____	
Distribution/ _____	
Availability Codes	
Dist	Avail and/or special
A	

DELAWARE RIVER BASIN

Name of Dam: Penn Lake Dam  
County & State: Luzerne County, Pennsylvania  
Inventory Number: PA 00542

6 National Dam Inspection Program. Penn Lake Dam (NDI ID Number PA-00542, DER ID Number 40-28), Delaware River Basin, Wright Creek, Luzerne County, Pennsylvania, Phase I Inspection Report.

11 Mar 79

PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM

12 70 P.

15 DACW 32-79-C-0010

Prepared by:

O'BRIEN & GERE ENGINEERS, INC.  
JUSTIN & COURTNEY DIVISION

For:

DEPARTMENT OF THE ARMY  
Baltimore District, Corps of Engineers  
Baltimore, MD 21203

410 760

slf

## PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigations, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through frequent inspections can unsafe conditions be detected, and only through continued care and maintenance can these conditions be prevented or corrected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the spillway design flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. The spillway design flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.



## PHASE I REPORT

### NATIONAL DAM INSPECTION PROGRAM

Name of Dam: Penn Lake Dam ID # PA 00542  
State Located: Pennsylvania  
County Located: Luzerne  
Stream: Wright Creek  
Coordinates: Latitude 41° 05.4', Longitude 75° 46.8'  
Date of Inspection: December 14, 1979

#### ASSESSMENT

Penn Lake Dam, owned by Carolyn D. and Robert H. Raymond (Penn Lake Association), is an earth embankment approximately 350 feet long and 44 feet high at its maximum section. The spillway consists of twelve 42-inch diameter, 20-foot long pipes located approximately 1,000 feet left (looking downstream) of the dam. Earth swales on both sides of the battery of pipes function as auxiliary spillways. The 56 acre reservoir is used for recreation by members of the Penn Lake Association.

Examination of the results of the hydrologic and hydraulic analyses indicates that the spillway (pipes and swales) is capable of passing 48 per cent of the Probable Maximum Flood (PMF) without overtopping of the embankment. Failure of the dam would increase the hazard of loss of life downstream of the dam. The capacity of the spillway system is therefore classified as "Seriously Inadequate". The dam is considered to be unsafe (non-emergency).

Based on visual observations made during the date of the inspection, the dam is considered to be in poor condition. There are seeps and rust colored water along the toe of the downstream embankment slope. The entire region immediately downstream of the dam is swampy. Bulges, depressions and embankment sloughing are evident on the downstream slope of the embankment. There are cut brush, stumps, and debris over the entire downstream slope. The upstream slope of the embankment is covered with heavy brush and there is a depression (Plate 4, Appendix E) near the left abutment. The riprap protection on the upstream and downstream slopes of the embankment is poorly graded and sparse in many areas.

Recommendations and remedial measures are as follows:

#### a. Facilities

1. The capacity of the spillway system should be increased in accordance with the results of detailed hydrologic and hydraulic studies.

2. A subsurface investigation program should be initiated to determine the composition and in situ properties of the earth embankment and foundation materials and to determine the stability of the dam. The investigations should be supervised by a licensed professional engineer experienced in the design and construction of dams.

3. Piezometers should be installed in the boreholes to evaluate pore pressure development throughout the earth embankment and aid in determining the source of the seeps all along the toe of the downstream earth embankment slope.

4. The area at the downstream end of the reservoir drain system should be cleared of silt and debris. The drain system should then be appraised and repaired as needed. A means of positive closure at the upstream end of the reservoir drain system should be developed.

5. All brush, stumps, debris, etc. should be removed from the dam.

6. Decisions concerning the need to supplement the riprap protection, raise the top of the dam, and add additional spillway facilities, should await the results of the drilling program and further hydrologic/hydraulic analyses.

b. Operation and Maintenance Procedures

1. A downstream warning system should be developed; and during periods of heavy rainfall, the dam should be monitored and downstream residents alerted in the event of an impending failure.


2. The owner should develop and implement a maintenance and inspection checklist to insure that all items are maintained on a regular basis.

O'BRIEN & GERE ENGINEERS, INC.  
JUSTIN & COURTNEY DIVISION

*Will M. Heiser*

Will M. Heiser, P.E.  
Vice-President

Pennsylvania Registration # 006926-ENGINEER



Date: 16 Apr. 1979

Approved by: *G. K. Withers*

G. K. WITHERS  
Colonel, Corps of Engineers  
District Engineer

Date: 14 May 1979



*UPSTREAM VIEW OF THE DAM*



*DOWNSTREAM VIEW OF THE DAM*



## TABLE OF CONTENTS

	<u>PAGE</u>
SECTION 1 - PROJECT INFORMATION	
1.1 General	1
1.2 Description	1
1.3 Pertinent Data	2
SECTION 2 - ENGINEERING DATA	
2.1 Design	4
2.2 Construction	4
2.3 Operation	4
2.4 Evaluation	4
SECTION 3 - VISUAL INSPECTION	
3.1 Findings	5
SECTION 4 - OPERATIONAL FEATURES	
4.1 Procedures	6
4.2 Maintenance of the Dam	6
4.3 Maintenance of Operating Facilities	6
4.4 Warning System in Effect	6
4.5 Evaluation	6
SECTION 5 - HYDRAULICS AND HYDROLOGY	
5.1 Evaluation of Features	7
SECTION 6 - STRUCTURAL STABILITY	
6.1 Evaluation of Structural Stability	8
SECTION 7 - ASSESSMENT, RECOMMENDATIONS, PROPOSED REMEDIAL MEASURES	
7.1 Dam Assessment	9
7.2 Recommendations, Remedial Measures	9



TABLE OF CONTENTS  
(Continued)

PLATES

APPENDIX A -	CHECKLIST, ENGINEERING DATA, DESIGN CONSTRUCTION, OPERATION, PHASE I
APPENDIX B -	CHECKLIST, VISUAL INSPECTION, PHASE I
APPENDIX C -	HYDROLOGIC & HYDRAULIC DATA
APPENDIX D -	PHOTOGRAPHS
APPENDIX E -	DRAWINGS
APPENDIX F -	SITE GEOLOGY

PHASE I INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM  
PENN LAKE DAM  
NDI I.D. NO. PA-00542  
DER #40-28

SECTION 1

PROJECT INFORMATION

1.1 General

a. Authority. The Dam Inspection Act, Public Law 92-367, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a program of inspection of dams throughout the United States.

b. Purpose of Inspection. The purpose of this inspection is to evaluate the structural and hydraulic conditions of the Penn Lake dam and appurtenant structures, and to determine if the dam constitutes a hazard to human life or property.

1.2 Description of Project (Information obtained from the Pennsylvania Department of Environmental Resources (DER), Dam Safety Division)

a. Penn Lake Dam is an earth embankment, approximately 350 feet in length with a maximum height of 44 feet. The dam impounds a reservoir with a surface area of 56 acres and a storage capacity of 246 acre-feet at normal pool level. The top of the dam is 20 feet wide, the downstream side slope is approximately 1.75 horizontal to 1.0 vertical (1.75H:1V), and the upstream side slope is approximately 3H:1V. No information is available concerning the properties of the embankment materials. The upstream and downstream slopes of the dam are riprapped with 12 to 18 inches of stone.

The spillway consists of a battery of twelve, 42-inch diameter, 20-foot long, steel pipes located approximately 1,000 feet left (looking downstream) of the dam. Earth swales on both sides of the battery of pipes function as auxiliary spillways. The road, which is located around the perimeter of the lake, extends over the spillway pipes and across the top of the dam.

The reservoir drain system consists of a 36-inch steel pipe with a sluice valve located at the downstream toe of the dam. The sluice valve is housed in a concrete block structure.

b. Location. Penn Lake Dam is located on Wright Creek at a point about 4 miles north of White Haven, in Dennison Township, Luzerne County, Pennsylvania. The dam site is shown on the USGS Quadrangle entitled "White Haven, Pennsylvania" at coordinates N 41° 05.4, W 75° 46.8'. A regional location plan of Penn Lake Dam is enclosed as Plate 1, Appendix E.

c. Size Classification. Penn Lake Dam has a storage capacity of 80 million gallons (246 acre-feet) and a maximum height of 44 feet. The structure is in the intermediate size category.

d. Hazard Classification. There are about 12 private residences in the valley between Penn Lake Dam and the Lehigh River (a distance of about  $2\frac{1}{2}$  miles). The topography downstream of the dam is such that flood waters would be directed towards these homes resulting in probable loss of lives and extensive property damage. Therefore, the structure is in the "High" hazard category.

e. Ownership. The dam is owned by Carolyn J. and Robert H. Raymond (Penn Lake Association), Star Route Box 226, White Haven, Pennsylvania, 18661.

f. Purpose of Dam. The dam was originally built in 1905 for ice pondage. The reservoir is now used for recreation by the members of the Penn Lake Association.

g. Design and Construction History. The dam was built in 1905 by S.S. Staples for ice pondage. H.S. Smith of Wilkes Barre was the designer.

h. Normal Operating Procedures. The lake is normally maintained at Elevation 1333.0. The owner was not available to operate the reservoir drain sluice valve during the day of inspection.

1.3 Pertinent Data (From information supplied by Pennsylvania DER & USGS)

a.	<u>Drainage Area</u> (square miles)	7.0
b.	<u>Discharge at Dam Site</u> (cfs)	
	Reservoir drain system at normal pool Elev. 1333.0	130
	Reservoir drain system at top of dam Elev. 1337.5	140
	Ungated spillway at top of dam Elev. 1337.5	3,440
	Total spillway capacity at top of dam Elev. 1337.5	3,580
c.	<u>Elevation</u> (feet above MSL)	
	Spillway crest (normal, recreation pool)	1333.0
	Top of dam (at low point of top of dam)	1337.5
	Reservoir Drain Invert (inlet)	1299.0
	Reservoir Drain Invert (outlet)	1298.0 +
	Streambed at centerline of dam	1298.0 +
	Maximum tailwater	1305.0 +

d.	<u>Reservoir (miles)</u>	
	Length of normal, recreation pool	0.61
	Length of maximum non-overlapping pool	0.63
	Fetch at normal pool	0.33
e.	<u>Storage (acre-feet)</u>	
	Normal, recreation pool, Elev. 1333.0	246
	Top of dam at low point, Elev. 1337.5	500
f.	<u>Reservoir Surface Area (acres)</u>	
	Normal, recreation pool, Elev. 1333.0	56
	Top of dam at low point, Elev. 1337.5	71
g.	<u>Dam Data</u>	
	Type	Earth
	Length	350 feet
	Height	44 feet (maximum)
	Top width	20 feet
	Side Slopes	3H:1V (upstream); 1.75H:1V (downstream)
	Zoning	No
	Impervious core	No
	Cutoff	No
	Grout Curtain	No
h.	<u>Spillway</u>	
	Type	12, 42-inch steel pipes. Earth swales on each side of the steel pipe spillway acts as an auxiliary spillway.
	Width	42 feet at spring line of pipes plus swales 200 feet.
	Length	20 feet
	Crest elevation	1333.0±
	Gates	None
	Upstream channel	About 30 feet long, rock bottom, 2H:1V side slopes.
	Downstream channel	Follows a natural draw through a heavily wooded region.
i.	<u>Outlet Works</u>	
	Type	36-inch steel pipe
	Length	230 feet ±
	Closure	Sluice valve at downstream end.
	Access	Intake is submerged; outlet structure and operating mechanism are at the downstream toe.
	Regulating facilities	Hand operated sluice valve.



## SECTION 2

### ENGINEERING DATA

#### 2.1 Design

a. Data Available. The information available for review of Penn Lake Dam includes the following (all information obtained from the Pennsylvania DER main office files in Harrisburg, Pennsylvania):

1. Dam inspection reports beginning in 1912 and through the following years.
2. Photographs beginning in 1912 and through the following years.
3. "Application for Permit to Draw Dam or Other Body of Water in Accordance with the Act of 12-15-59", 1971.
4. Miscellaneous correspondence.
5. Sheet showing shoreline of reservoir prepared in 1949.

b. Design Features. The design features are discussed in Section 1.2.a and shown on Plates 3, 4, and 5 of Appendix E.

#### 2.2 Construction

The dam was built in 1905 by S.S. Staples for ice pondage. H.S. Smith of Wilkes Barre was the designer.

#### 2.3 Operation

Operation procedures appear to be limited to those necessary to draw down the reservoir by means of the sluice valve located in a concrete block shed at the downstream toe of the dam. There is no evidence that operating procedures have been written for this structure.

#### 2.4 Evaluation

a. Availability. Very limited material is available. The one sketch of the impoundment area is enclosed as Plate 2 in Appendix E.

b. Adequacy. Although design and construction information is minimal, a Phase I evaluation is considered reasonable based on the revealing conditions observed during the field inspection.

c. Validity. There appears to be no reason to question the validity of the limited data available.

## SECTION 3

### VISUAL INSPECTION

#### 3.1 Findings

a. General. The field inspection of the Penn Lake Dam took place on December 14, 1978. The reservoir water surface elevation was approximately 1333.0 during the inspection. No underwater areas were inspected. The observations and comments of the field inspection team are in the checklist which is Appendix B of this report. The appearance of the facility indicates that the dam and its appurtenances are marginally maintained.

b. Dam. There are numerous bulges and depressions of more than a foot which form an undulating pattern along both the upstream and downstream slopes and the top of the dam. A survey revealed that the top of the dam elevation varies as much as 4.5 feet along the 350-foot length of the embankment. There is also some embankment sloughing on the downstream slope. It is difficult to appraise the extent of the undulations, sloughing, and what is left of the riprap facing on both the upstream and downstream slopes of the dam because of cut trees and debris on the slopes. There are seeps and murky rust colored water along the toe of the downstream embankment slope. The entire region immediately downstream of the dam is swampy.

c. Appurtenant Structures. The spillway, which consists of a battery of twelve 42-inch diameter, 20-foot long pipes, located approximately 1,000 feet left (looking downstream) of the dam, is seriously inadequate. There are no trashracks upstream of the spillway pipes to prevent debris from reducing the flow. Earth swales on both sides of the battery of pipes function as auxiliary spillways.

The sluice valve of the reservoir drain system is assumed to be in a partially opened position judging from the amount of water flowing in the vicinity of the concrete block structure which houses the sluice valve.

d. Reservoir. Area reconnaissance of the reservoir disclosed no evidence of excessive siltation, slope instability, or other features that would significantly affect the storage capacity of the reservoir. The slopes along the perimeter of the reservoir are vegetated and on gradients of less than ten per cent.

e. Downstream Channel. For about 80 per cent of the 2.5 miles from Penn Lake Dam to the Lehigh River, Wright Creek flows through a heavily wooded region. The balance of the distance is through meadows. There is one highway bridge about 2 miles downstream of the dam. The channel gradient averages about 1.4 per cent for the entire 2.5 miles. There are about a dozen homes within the potential damage area along Wright Creek downstream of Penn Lake Dam.

## SECTION 4

### OPERATIONAL FEATURES

#### 4.1 Procedures

Operational procedures have been covered in Section 1.2.h. Written operating procedures were not made available. Normal operating procedures for this structure do not require a dam tender.

#### 4.2 Maintenance of the Dam

Attempts to contact the owner of the dam were unsuccessful. The dam appears to be marginally maintained.

#### 4.3 Maintenance of Operating Facilities

No operating mechanism for the sluice gate was visible during the inspection. It is assumed that any operating mechanism would be housed in the inaccessible concrete block structure at the downstream end of the reservoir drain conduit. The sluice valve is maintained by the Penn Lake Association. Further discussion of the maintenance of the sluice valve is covered in Section 2.3.

#### 4.4 Warning System in Effect

There is no evidence that a formal warning system or procedures to be followed during periods of exceedingly heavy rainfall is in effect.

#### 4.5 Evaluation of Operational Adequacy

The operation and maintenance procedures appear to be marginal for the Penn Lake Dam. An operation and maintenance check list should be developed and implemented by the owner.

A formal warning system should be implemented because of the probability of loss of life and extensive property damage downstream in the event of a failure of the dam.

The dam is accessible under all weather conditions for inspection and emergency action.



## SECTION 5

### HYDRAULICS AND HYDROLOGY

#### 5.1 Evaluation of Features

a. Design Data. There is no original design information available. The drainage area contributing to Penn Lake Dam is about 4.5 miles long and averages about 1.5 miles wide. Ground elevations range from 2060 to 1333. The slopes of the watershed adjacent to the reservoir are all less than ten per cent. The watershed is nearly 100 per cent wooded. The runoff characteristics of the watershed may undergo change in the future as a result of development.

The spillways are capable of handling a discharge of 3440 cfs. However, the SDF for this "Intermediate" size dam, with a "High" hazard classification, is the PMF which has a peak inflow of 7690 cfs and a peak outflow of 7630 cfs. The PMF hydrograph was routed through the reservoir with the starting water surface elevation at the crest of the spillway, Elev. 1333.0. The maximum water surface elevation in the reservoir resulting from the PMF routing would be 5.6 feet above the spillway crest and 1.1 feet above the lowest point of the top of the dam.

For further information, refer to the computations, data, and printouts included in Appendix C.

b. Experience Data. There is no evidence that rainfall or water level records are kept for this dam.

c. Visual Observations. The major spillway elements, which consist of twelve, 42-inch steel pipes and adjacent earth swales, showed no visible signs of deterioration.

Further observations are given in Appendix B.

d. Overtopping Potential. The SDF is the PMF for this "Intermediate" size, "High" hazard structure. Examination of the results of the hydrologic and hydraulic analysis indicates that the spillways are capable of passing 48 per cent of the PMF without overtopping of the embankment. (See Appendix C for computations).

e. Spillway Adequacy. A dam break analysis was performed to evaluate the increased "hazard to loss of life downstream from the dam from that which would exist just before overtopping failure" (ETL 1110-2-234, 10 May, 1978). According to the analysis, failure of the Penn Lake Dam during the occurrence of 50 per cent of the PMF would increase the depth of overbank flow from 3.0 feet to 5.2 feet in the hazard area. The peak discharge at the hazard area would increase from 3,860 cfs to 11,150 cfs. Failure of the dam is considered to significantly increase the hazard to loss of life. Therefore, the spillway of the Penn Lake Dam is classified as "seriously inadequate".



## SECTION 6

### STRUCTURAL STABILITY

#### 6.1 Evaluation of Structural Stability

a. Visual Observations. There are surface undulations of more than a foot along the top of the dam and the side slopes of the embankment which could be the result of settlement or poor construction methods. The riprap facing on both the upstream and downstream slopes of the embankment is obscured by the cut trees and debris on the slopes. Seeps and rust colored water are evident along the toe of the downstream embankment slope. The entire region immediately downstream of the dam is swampy.

Due to the lack of information concerning the embankment and foundation materials, the stability of the dam cannot be properly assessed.

b. Design and Construction Data. There are no design and construction data available. It is known that the structure was originally designed in 1905 by H.S. Smith of Wilkes Barre and it was built by S.S. Staples during the same year.

c. Operating Records. There is no evidence that operating records are maintained at this structure.

d. Post Construction Changes. Since there are no records of the original design and construction, there is no way of knowing exactly what constituted the original structure. Sometime after the original construction, the dam was increased in height from 24 feet to 44 feet, and the spillway was developed approximately 1,000 feet left (looking downstream) of the dam. There is no documentation of when these modifications were made. From the DER files, information is available on maintenance repair work done on the dam through the years.

e. Seismic Stability. Penn Lake Dam is located in Seismic Zone 1 of the "Seismic Zone Map of Contiguous States". Normally, it can be considered that if a dam in this zone is stable under static loading conditions, it can be assumed safe for any expected Zone 1 earthquake conditions.

## SECTION 7

### ASSESSMENT, RECOMMENDATIONS, PROPOSED REMEDIAL MEASURES

#### 7.1 Dam Assessment

a. Evaluation. Based on visual observations made during the date of the inspection, the dam is considered to be in poor condition. There are seeps and murky rust colored water evident along the toe of the downstream embankment slope. The entire region immediately downstream of the dam is swampy. Bulges and depressions are evident on the downstream slope of the embankment and there is some embankment sloughing. There are cut brush, stumps, and debris over the entire downstream slope. The upstream slope of the embankment is covered with heavy brush and there is a depression (Plate 4, Appendix E) near the left abutment. The riprap protection on the upstream and downstream slopes is poorly graded and sparse in many areas.

The SDF is the PMF. Examination of the results of the hydrologic and hydraulic analysis indicates that the spillway is capable of passing 48 per cent of the PMF without overtopping of the embankment. Failure of the dam would increase the hazard to loss of life downstream of the dam. Therefore, the capacity of the drop spillway is classified as "seriously inadequate". The dam is considered to be unsafe (non-emergency).

It is assumed the sluice valve of the reservoir drain system is partially opened. This observation is based on the amount of water flowing in the vicinity of the concrete block structure at the toe of the downstream embankment slope which houses the sluice valve.

b. Adequacy of Information. Although design and construction information is minimal, a Phase I evaluation is considered reasonable based on the revealing conditions observed during the field inspection.

c. Urgency. The remedial measures recommended in Section 7.2 should be effected immediately.

d. Necessity for Further Evaluation. Further investigation should be performed to determine the source of the seeps, rust colored water, undulations, and sloughing of the embankment. Detailed hydrologic and hydraulic studies should be made to determine the necessity to increase the spillway system for this structure.

#### 7.2 Recommendations and Remedial Measures

##### a. Facilities.

1. The capacity of the spillway system should be increased in accordance with the results of detailed hydrologic and hydraulic studies.

2. A subsurface investigation program should be initiated to determine the composition and in situ properties of the earth embankment and foundation materials and to determine the stability of the dam. The investigations should be supervised by a licensed professional engineer experienced in the design and construction of dams.

3. Piezometers should be installed in the boreholes to evaluate pore pressure development throughout the earth embankment and aid in determining the source of the seeps all along the toe of the downstream earth embankment slope.

4. The area at the downstream end of the reservoir drain system should be cleared of silt and debris. The drain system should then be appraised and repaired as needed. A means of positive closure at the upstream end of the reservoir drain system should be developed.

5. All brush, stumps, debris, etc. should be removed from the dam.

6. Decisions concerning the need to supplement the riprap protection, raise the top of the dam, and add additional spillway facilities, should await the results of the drilling program and further hydrologic/hydraulic analyses.

b. Operation and Maintenance Procedures

1. Because there are about a dozen homes located along Wright Creek between Penn Lake Dam and the Lehigh River (a distance of about  $2\frac{1}{2}$  miles), a downstream warning system should be developed, and during periods of heavy rainfall, the dam should be monitored and downstream residents alerted in the event of an impending failure.

2. The owner should develop and implement a maintenance and inspection checklist to insure that all items are maintained on a regular basis.



APPENDIX

A

Check List Engineering Data  
Design, Construction, Operation  
Phase I

NAME OF DAM Penn Lake Dam  
 ID # PA 00542

CHECK LIST  
 ENGINEERING DATA  
 DESIGN, CONSTRUCTION, OPERATION  
 PHASE I

Sheet 1 of 4

REMARKS

ITEM

AS-BUILT DRAWINGS

There are no "As-Built" drawings. The only drawing in the DER files is a sheet showing the shoreline of the reservoir prepared 2/49

REGIONAL VICINITY MAP

Refer to Appendix E, Plate 1

CONSTRUCTION HISTORY

The dam was built in 1905 by S. P. Staples and his associates for the purpose of securing ice pondage. The structure was designed by H. S. Smith, Wilkes Barre, Pa.

TYPICAL SECTIONS OF DAM

Not Available

OUTLETS - PLAIN

DETAILS

Not Available

CONSTRAINTS

DISCHARGE RATINGS

Not Available

RAINFALL/RESERVOIR RECORDS

Not Available

ITEM	REMARKS
DESIGN REPORTS	<i>No design data available.</i>
GEOLOGY REPORTS	<i>None provided in DER files. Refer to Appendix F of this report.</i>
DESIGN COMPUTATIONS HYDROLOGY & HYDRAULICS DAM STABILITY SEEPAGE STUDIES	<i>No data available No data available No data available No data available</i>
MATERIALS INVESTIGATIONS BORING RECORDS LABORATORY FIELD	<i>No information available</i>
POST-CONSTRUCTION SURVEYS OF DAM	<i>None</i>
BORROW SOURCES	<i>There is no record of where borrow material came from.</i>



ITEM	REMARKS
------	---------

MONITORING SYSTEMS

None

MODIFICATIONS

Sometime after the original construction the dam was measured in height from 24' to 44'. There is no documentation of when this was done. <sup>Switney</sup> was developed approx. 1000 ft. left of the dam, sometime after the original construction

HIGH POOL RECORDS

None available

POST CONSTRUCTION ENGINEERING STUDIES AND REPORTS

None

PRIOR ACCIDENTS OR FAILURE OF DAM DESCRIPTION REPORTS

Letter written 12/29/91 warns of impending failure of the site. This led to state inspection of the dam and remedial repairs in 1912

MAINTENANCE OPERATION RECORDS

Correspondence through the years (from DER files) gives information about sporadic maintenance work that was done on the structure. There are no operating records available.

ITEM	REMARKS
SPILLWAY PLAN	Refer to Appendix E for details
SECTIONS	
DETAILS	
OPERATING EQUIPMENT PLANS & DETAILS	No information available
MISCELLANEOUS	<p>Material in DER files:</p> <ol style="list-style-type: none"> <li>1. Dam inspection reports through the years.</li> <li>2. Photographs related to the structure from 1912 through 1965.</li> <li>3. "Application for Permit to Draw Dam or Other Body of Water" (1970)</li> <li>4. Miscellaneous correspondence</li> <li>5. Sheet showing structure of reservoir prepared 1949.</li> </ol>

APPENDIX

B

Check List

Visual Inspection

Phase I



CHECK LIST  
VISUAL INSPECTION  
PHASE I

Sheet 1 of 11

Name Dam Penn Lake Dam County Lucerne State Pennsylvania National ID # DA-00542  
Type of Dam Earth Fill Hazard Category High  
Date(s) Inspection Dec 14, 1913 Weather Cloudy, Cold Temperature ~30°F

Pool Elevation at Time of Inspection 1333 ± M.S.L. Tailwater at Time of Inspection 1290 ± M.S.L.

Inspection Personnel:

George A. Elias David B. Campbell Leonard R. Beck  
Leonard R. Beck Recorder

Remarks:

We were not successful in contacting anyone associated with the dam.

# CONCRETE/MASONRY DAMS

Sheet 2 of 11

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
ANY NOTICEABLE SEEPAGE	N/A	
STRUCTURE TO ABUTMENT/EMBANKMENT JUNCTIONS	N/A	
DRAINS	N/A	
WATER PASSAGES	N/A	
FOUNDATION	N/A	

# CONCRETE/MASONRY DAMS

Sheet 3 of 11

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS CONCRETE SURFACES	N/A	
STRUCTURAL CRACKING	N/A	
VERTICAL AND HORIZONTAL ALIGNMENT	N/A	
MONOLITH JOINTS	N/A	
CONSTRUCTION JOINTS	N/A	



EMBANKMENT

Sheet 4 of 11

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS	Could not tell because there is so much cut trees and debris on the slopes and a hard surface road runs along the top of the dam.	clean all of the cut trees and debris off the slopes of the dam.
UNUSUAL MOVEMENT OR CRACKING AT OR BEYOND THE TOE	None observed	None
SLOUGHING OR EROSION OF EMBANKMENT AND ABUTMENT SLOPES	There appears to be sloughing especially on the downstream slope. It is difficult to tell how much sloughing has occurred because there is so much cut trees and debris on the slopes.	A borings program should be initiated to determine the composition and in situ properties of the embankment and foundation materials & to determine the stability of the dam.
VERTICAL AND HORIZONTAL ALIGNMENT OF THE CREST	There are numerous bulges and depressions which form an undulating pattern along both the upstream and downstream slopes and the top of the dam.	Piezometers should be installed in the bore holes to evaluate pore pressure development throughout the embankment.
RIPRAP FAILURES	It is difficult to tell what is left of the riprap facing on both the upstream and downstream faces because of the cut trees and debris on the slopes.	

EMBANKMENT

Sheet 5 of 11

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
-----------------------	--------------	----------------------------

JUNCTION OF EMBANKMENT AND ABUTMENT, SPILLWAY AND DAM	It is difficult to assess the situation at the junction of the embankment and abutment because of the excessive debris and brush on the slopes. The spillway is about 100 feet below the embankment.	refer to comments on sheet 4/11
---	---	------------------------------------

ANY NOTICEABLE SEEPAGE	There is seepage of varying degrees all along the downstream face	refer to comments on sheet 4/11. Assessment should be given immediately to foundation and embankment grouting & for a completely new internal drainage system.
------------------------	--	---

STAFF GAGE AND RECORDER	None	None
-------------------------	------	------

DRAINS	None observed	None
--------	---------------	------

# OUTLET WORKS

Sheet 6 of 11

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CRACKING AND SPALLING OF CONCRETE SURFACES IN OUTLET CONDUIT	Outlet conduit could not be observed.	Draw down impoundment so that entire reservoir drain system can be examined.
INTAKE STRUCTURE	Intake structure could not be observed because it was under water.	"
OUTLET STRUCTURE	Outlet of reservoir drain system could not be observed because it was under a locked concrete block structure.	"
OUTLET CHANNEL	It winds through the woods for about 200 feet where it joins the channel for the spillway discharges.	Could be realigned to flow directly away from the dam.
EMERGENCY GATE	It is assumed the sluice valve is in approximately open position judging from the amount of water flowing in the vicinity of the concrete block structure which houses the gate.	Sluice valve should be repaired as needed.



# UNGATED SPILLWAY

Sheet 7 of 11

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONCRETE WEIR	Weir is actually the invert of 12, 42 inch, 20 foot long pipes. The invert of the pipes is Elev. 1333.0. A road is built on top of the pipes. The surface of the road is about 5 feet above the pipe invert.	This spillway is of very limited capacity. Swales on both sides of spillway pipes act as auxiliary spillways.
APPROACH CHANNEL	Approach channel is only about 30 feet in length with limited obstruction from timber bridge.	"
DISCHARGE CHANNEL	Follows natural drain through heavily wooded region. Channel gradient is on about a 2 percent slope.	Timbered drain presents too much of an obstruction to flow.
BRIDGE AND PIERS	Timber bridge (pedestrian traffic) and highway culvert (12, 42-inch, 20-foot long pipes).	Restrict flow, needs to be opened up.

GATED SPILLWAY

Sheet 8 of 11

<u>VISUAL EXAMINATION OF</u>	<u>OBSERVATIONS</u>	<u>REMARKS OR RECOMMENDATIONS</u>
CONCRETE SILL	N/A	
APPROACH CHANNEL	N/A	
DISCHARGE CHANNEL	N/A	
BRIDGE AND PIERS	N/A	
GATES AND OPERATION EQUIPMENT	N/A	

INSTRUMENTATION

Sheet 9 of 11

REMARKS OR RECOMMENDATIONS

OBSERVATIONS

MONUMENTATION/SURVEYS

N/A

OBSERVATION WELLS

N/A

WEIRS

N/A

PIEZOMETERS

N/A

OTHER

N/A

RESERVOIR

Sheet 10 of 11

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
-----------------------	--------------	----------------------------

SLOPES

All slopes are less than 10%.  
Entire shoreline of reservoir is  
residentially developed.

None

SEDIMENTATION

Probably won't be too much  
additional sediment because  
because the entire shoreline is  
residentially developed. A certain  
amount of sediment probably was  
deposited in the reservoir when all  
the structures were built around the lake.

None



DOWNSTREAM CHANNEL

Sheet 11 of 11

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONDITION (OBSTRUCTIONS, DEBRIS, ETC.)	For about 80% of the 2.5 miles from Penn Lake Dam to the Lehigh and Wright Creek flows through a heavily wooded region. The balance of the distance is through meadows. There is one highway bridge about 2.0 miles downstream of Penn Lake Dam.	An estimated "1" value is about 0.06 for the entire 2.5 miles
SLOPES	The channel gradient averages about 1.4 % for the entire 2.5 miles from Penn Lake Dam to the confluence of Wright Creek with the Lehigh River.	None
APPROXIMATE NO. OF HOMES AND POPULATION	There are about a dozen homes and approximately 60 people.	A formal warning system should be developed and implemented. Procedures for evacuating people within the potential flood area should be implemented.

APPENDIX

C

Hydrologic & Hydraulic Data

## Table of Contents APPENDIX C

### Hydraulics & Hydrologic Data

PMP Calculations	Sheet 1
Hyder Coefficients	Sheet 1
Spillway Discharge Computations Through Pipes	Sheet 2
Spillway Discharge Flow Areas Through Gates	Sheets 2 & 3
Flow Over Top of Dam	Sheet 3
Stage - Discharge Computation Summary	Sheet 4
Stage - Area, Stage - Storage Calculations	Sheet 5
Reservoir Draw Discharge & X-sec. & Damage Area	Sheet 5
Stage - Area, Stage - Storage Plots	Sheet 6
HEC - I Dam Safety Version Computer Output	Sh. 7-11
HEC - I Dam Safety Version Computer Output with Dam Break	Sh 12-18



O'BRIEN & GERE

SUBJECT

PENN LAKE DAM

SHEET

1

BY

RRB

DATE

3/5/79

JOB NO

13 3/5/79

HYDROLOGY CALC.

DRAINAGE AREA: 7.0 SQUARE MILES

PMP CALCULATIONS (HMS REPORT 33)

AREA IS IN ZONE 1

24 HR., 200 SQ. MI. RAINFALL = 22"

<u>HR.</u>	<u>%</u>	<u>RAINFALL</u>	<u>ΔRF</u>
6	111	24.4"	24.4"
12	123	21.1"	2.7"
24	133	29.3"	2.2"
48	142	31.2"	1.9"

SNYDER COEFFICIENTS

FROM INFO. PROVIDED BY COE,  
FOR THE DELAWARE RIVER BASIN, ZONE 2:

$$C_p = 0.45$$

AND  $C_t = 2.1$

$$t_p = C_t (L \cdot L_{ca})^{0.3}$$

$$L \approx 5.3 \text{ miles}$$

$$L_{ca} \approx 2.8 \text{ miles}$$

$$t_p = 2.1 (5.3 \cdot 2.8)^{0.3} = 4.72 \text{ HR.}$$



SUBJECT

Penn Lake Dam, Stage 10 Discharge

SHEET

2

BY

JH

DATE

2/23/79

JOB NO

1 R25 2/25/79

12 Discharge Pipes

Pipe Flow

Assume Pipe Invert El. 1332.0 (Normal Pond)

@ El. 1324.5 (Normal h. point of outlet)

ES 97.37 (SCS, NEH-D)

For 1.50' of H<sub>2</sub>O in a 25' pipe  $\frac{d}{D} = \frac{1.5}{25} = 0.06$

For Normal Discharge

$$\frac{21 Q_{nd}}{2.42} = 0.178$$

$$Q_{nd} = 0.178 \times 2.42 = 0.43$$

Assume D = 25'

$f = 0.015$

$n = 0.015$

$$Q_{nd} = 0.178 \times \frac{2.42}{0.015} = 29.7 \text{ cfs} \approx 34 \text{ cfs}$$

For 12 pipes  $34 \times 12 = 408 \text{ cfs}$

Full Pipe Flow

$$Q_p = C_p H_p^{1/2}$$

$$C_p = A_p \sqrt{\frac{2g}{1 + K_e + K_o + K_{Lp}}}$$

$K_e \approx 1.0$  (Entrance loss)

$K_o \approx 0.5$  (Exit loss)

$K_p = 0.00154$  (Pipe loss)

$L_p = \text{Length of pipe}$

$A_p = 9.62 \times 12 = 115.44$

42" dia pipe

Assume invert outlet El. 1332.8

$$C_p = 115.44$$

With H<sub>2</sub>O @ El. 1337.5 in reservoir

$$Q_p = 568.4 \times 2.75^{1/2}$$

$$C_p = 568.4$$

$$Q_p = 977 \text{ cfs}$$

With H<sub>2</sub>O @ El. 1340.0 in reservoir

$$Q_p = 568.4 \times 3.45^{1/2}$$

$$Q_p = 1327 \text{ cfs}$$

Discharge Through Siphons

Right side Siphon

H<sub>2</sub>O to El. 1337.5 @ Siphon Invert El. 1324.5

Find equivalent rect. x-sec. of flow

Dimensions (Ft)

X-sec. Area (Ft<sup>2</sup>)

$$\frac{3 \times 4.5}{2}$$

$$= 72$$

$$\frac{50 (2.5 \times 2.7)}{2}$$

$$= 142.5$$

$$\frac{2.7 \times 103}{2}$$

$$= 137.1$$

$$\frac{353.6 \text{ Ft}^2}{3 \text{ Ft (Depth)}}$$

$$= 118 \text{ Ft}^2$$

Left side Siphon

H<sub>2</sub>O to El. 1337.5 @ Siphon Invert El. 1324.5

Dimensions (Ft)

X-sec. Area (Ft<sup>2</sup>)

$$\frac{3 \times 4.5}{2}$$

$$= 64.5$$

$$\frac{25 (2.5 \times 2.7)}{2}$$

$$= 66.8$$

$$\frac{2.5 \times 45}{2}$$

$$= 60.0$$

$$\frac{191.3 \text{ Ft}^2}{3 \text{ Ft (Depth)}}$$

$$= 64 \text{ Ft}^2$$

of flow

SUBJECT	SHEET	BY	DATE	JOB NO.
Lower Lake Dam, Storage, Spillway	3	JH	2/23/79	

✓ RRL 3/5/79

Discharge Through Spillway & Over Spillway Pipes

Right Side Spillway

H<sub>2</sub>O to El. 1340.0 & Spillway Surface El. 1334.5

Dimensions (Ft.)

X-sec Area (Ft<sup>2</sup>)

$$\frac{2.4 + 5.5}{2} \times 50 = 197.5$$

$$\frac{5.5 + 5.2}{2} \times 50 = 267.5$$

$$\frac{5.2 \times 175}{2} = 507.0$$

$$\frac{912.0}{5.2} \approx 174 \text{ Ft.}$$

Left Side Spillway

H<sub>2</sub>O to El. 1340.0 & Spillway Surface El. 1334.5

Dimensions (Ft.)

X-sec Area (Ft<sup>2</sup>)

$$\frac{2 + 5.5}{2} \times 50 = 187.5$$

$$\frac{5.5 + 5}{2} \times 50 = 131.2$$

$$\frac{5 \times 96}{2} = 240.0$$

$$\frac{558.7}{5.5} \approx 102 \text{ Ft.}$$

Flow Over Spillway Pipes

H<sub>2</sub>O to El. 1340.0 & El. Surface Over Pipes El. 1333.0 + El. 1337.6

Net H = 2.2', Width of Spillway System 60'

Flow Over Top of Dam

H<sub>2</sub>O to El. 1340.0 Low H. Top of Dam El. 1337.4

$$\frac{2.3 \times 41}{2} = 54.0$$

$$\frac{2.3 + 2.6}{2} \times 50 = 122.5$$

$$\frac{2.6 + 1.1}{2} \times 50 = 92.5$$

$$\frac{1.1 + 0.5}{2} \times 50 = 40.0$$

$$\frac{0.5 \times 16}{2} = 4.0$$

$$\frac{313.0}{2.2} \approx 120 \text{ Ft.}$$

SUBJECT	SHEET	BY	DATE	JOB NO.
Rain Lake Drain, Stage B, Discharge	4	C	2/22/79	

1225 3/5/79

Elev	Spillway Pipe Diam. (ft)	Spillway Pipe Length (ft)	Spillway Pipe Area (sq ft)	Spillway Pipe Velocity (ft/sec)	Spillway Pipe Discharge (cfs)	Spillway Pipe Head (ft)	Spillway Pipe Loss (ft)	Spillway Pipe Total Head (ft)	Spillway Pipe Total Discharge (cfs)	Spillway Pipe Total Head (ft)
1323.0	0	0	0	0	0	0	0	0	0	0
1324.5	1.5	405	0	0	0	0	0	0	0	0
1327.5	4.5	947	3.0	8.5	1595	0	0	0	0	0
1340.0	7.0	1327	5.5	24.21	5936	2.2	2.2	2.2	1303	12670

1) Refer to Sk. 2

2) Refer to Sk. 2

3) Broad crested weir,  $C = 2.60$  used in formula  $Q = CLH^{3/2}$

4)  $L = 64'$ , refer to Sk. 2

5)  $L = 118'$ , refer to Sk. 2

6)  $L = 126'$ , refer to Sk. 3

7)  $L = 149'$ , refer to Sk. 3

8) Ave. H over spillway pipes,  $L = 80'$ , refer to Sk. 3

9)  $L = 120'$ , refer to Sk. 3

Stage	Surface Area (Ac.)	Storage (Ac. Ft.)
1293	0	0
1333 1/2	56	246 3/4
1340	84	736
1360	168	2416
1/ Normal reservoir surface elevation taken from USGS White Haven, Pa. 7 1/2' Quadrangle		
2/ Storage capacity supplies by DER (2000000 gal = 246 Ac. Ft.)		

Reservoir Drain Discharge:

$$C_d = k_p \sqrt{\frac{2g}{1 + K_e + K_v + K_f}}$$

$$C_d = 7.07 \sqrt{\frac{2g}{1 + 0.5 + 0.017 + 0.25}}$$

$$C_d = 7.07 \times 3.16$$

$$C_d = 22.34$$

With normal pool @ El. 1333.0

$$\text{head to } \frac{1}{2} \text{ gate valve} = 1333.0 - 1299.5 = 33.5'$$

$$Q_p = C_d H_p^{1/2}$$

$$Q_p = 22.34 \times 33.5^{1/2}$$

$$Q_p = 129.3 \text{ USE } 130 \text{ cfs}$$

$$V = 7.07 \text{ ft/s}$$

7.07 ft/s (very low velocity, assume interior of very smooth)

$K_e = 1.0$  (Entrance loss coeff.)

$K_v = 0.5$  (Exit loss coeff.)

$K_f = 0.0171$  (Pipe loss coeff, ES-42, 365)

$$L_p = 230'$$


known invert outlet = El. 1298.0

Top of dam @ 200 ft El. 1341.9

(see El. 1342.0)

known  $\frac{1}{2}$  gate valve @ El. 1299.5

### Cross-Section Downstream of Dam & Area





SUBJECT

Renii Lake Dam

SHEET

6

BY

FH

DATE

2/28/77

JOB NO

Stage - Storage Plot  
#

Stage - Area Plot

Stage (feet above 1154)

1260

1240

1220

1200

Stage - Area

Stage Storage

500

1000

1500

2000

2500

Storage (Ac. Ft.)

0

50

100

150

200

Area (Acres)

35



85

NATIONAL DAM INSPECTION PROGRAM  
PENN LAKE DAM  
PMF HYDROGRAPH

	JOB SPECIFICATION	IPRT	INSTAN
DAY	MTRC	-6	0
NMIN	U		
U	U		
TRACE	LHO-T		
WMT	U		
JPFR	U		
S			

MULTI-PLAN ANALYSES TO BE PERFORMED  
NPLAN= 1 NRATIO= 7 LRATIO= 1

1.00	.90	.80	.70	.60	.50	.40	.30	.20	1105 =
------	-----	-----	-----	-----	-----	-----	-----	-----	--------

1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28  
29  
30  
31  
32  
33  
34  
35  
36  
37  
38  
39  
40  
41  
42  
43  
44  
45  
46  
47  
48  
49  
50  
51  
52  
53  
54  
55  
56  
57  
58  
59  
60  
61  
62  
63  
64  
65  
66  
67  
68  
69  
70  
71  
72  
73  
74  
75  
76  
77  
78  
79  
80  
81  
82  
83  
84  
85  
86  
87  
88  
89  
90  
91  
92  
93  
94  
95  
96  
97  
98  
99  
100

# SUB-ALPHA FUNCTION COMPUTATION

REMARKS: 1) K. STEWART

ISTAG	ICOMP	IECON	ITAPE	JPLT	JPRY	INAME	ISTAGE	IAUTO
				0	0	1	0	0

TYPE	TABLE	SNAP	MYCROGRAPH DATA	RATIO	ISNOW	ISAME	LOCAL
				0.038	0	0	0

PRECIP DATA	R0	R12	-24	H48	R72	R96
145	142.00	133.00	142.00	142.00	0.00	0.00

THESE COMPTES SONT EN VOIE D'APPROBATION

LOSS DATA	RTIOK	STRTLT	CNSTL	ALSMX	RTIMP
0.00	0.00	0.00	0.00	0.00	0.00

```

UNIT HYDROGRAPH DATA
13- 4-72 CPE = .43 NTA= 0

```

```

RECESSION DATA
RCS= -.05
RTION= 2.00

```

RELATIVE HUMIDITY	PERIOD	ORDINATES	LAG	HOURS	CP	VOL
100	135	377	402	353	310	238
90	130	377	402	353	310	272
80	125	377	402	353	310	73
70	120	377	402	353	310	84
60	115	377	402	353	310	45
50	110	377	402	353	310	20
40	105	377	402	353	310	23
30	100	377	402	353	310	26
20	95	377	402	353	310	31
10	90	377	402	353	310	34
0	85	377	402	353	310	43
	80	377	402	353	310	50
	75	377	402	353	310	50
	70	377	402	353	310	50
	65	377	402	353	310	50
	60	377	402	353	310	50
	55	377	402	353	310	50
	50	377	402	353	310	50
	45	377	402	353	310	50
	40	377	402	353	310	50
	35	377	402	353	310	50
	30	377	402	353	310	50
	25	377	402	353	310	50
	20	377	402	353	310	50
	15	377	402	353	310	50
	10	377	402	353	310	50
	5	377	402	353	310	50
	0	377	402	353	310	50

$\overline{b} \frac{45}{9}$ 

100

# SYNOGRAPH ROUTING

ROUTING THROUGH PENN LAKE

ISTAG	ICDAP	IECUN	ITAPE	JPLT	JPRT	INAME	ISTAGE	IAUTO
A2	1	0	0	0	0	1	0	0
CLS5	AVG	ROUTING DATA						
0.00	0.00	IMES	ISAME	IOPT	IPMP		LSTR	
		1	1	0	0		0	
NSIPS	INSTCL	LAG	AMSKA	X	TSK	STORA	ISPRAT	
		0	0.000	0.000	0.000	-1333.	-1	

STAGE	1335.00	1335.00	1337.50	1340.00	1350.00
#LOC	0.00	410.00	340.00	12000.00	151000.00
CAPACITY	0	245	700	240	
EXP. FREQ	1335	1335	1340	1350	

CYCL	EXP	COUL	CAREA	EXPL
13JJ.0	0.0	0.0	0.0	0.0

PEAK OUTFLOW IS	1471.0	AT TIME	42.00 HOURS
PEAK OUTFLOW IS	2239.0	AT TIME	42.00 HOURS
PEAK OUTFLOW IS	2708.0	AT TIME	42.00 HOURS
PEAK OUTFLOW IS	3004.0	AT TIME	42.00 HOURS
PEAK OUTFLOW IS	4714.0	AT TIME	44.00 HOURS
PEAK OUTFLOW IS	5445.0	AT TIME	42.00 HOURS
PEAK OUTFLOW IS	7130.0	AT TIME	42.00 HOURS
PEAK OUTFLOW IS	8200.0	AT TIME	42.00 HOURS
PEAK OUTFLOW IS	10346.0	AT TIME	42.00 HOURS



34 10

PLAN FLOW AND STIMARE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS  
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)  
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

STATION	PLAN FLOW	AREA	RATIOS APPLIED TO FLOWS								
			RATIO 1	RATIO 2	RATIO 3	RATIO 4	RATIO 5	RATIO 6	RATIO 7	RATIO 8	RATIO 9
			.20	.30	.40	.50	.60	.70	.80	.90	1.00
WATERGATE AT	1	7.00	1.537	2306	3074	3843	4612	5380	6149	6918	7686
	(	( 14.13)	( 43.53)	( 65.33)	( 87.06)	( 108.83)	( 130.59)	( 152.36)	( 174.12)	( 195.89)	( 217.65)
WATER TO	1	7.00	1.491	2239	2986	3904	4714	5338	6136	6885	7634
	(	( 14.13)	( 42.21)	( 63.39)	( 84.56)	( 110.55)	( 133.49)	( 151.14)	( 173.75)	( 194.97)	( 216.18)

# SUMMARY OF DAM SAFETY ANALYSIS

94 LL

PLAN 1 .....	ELEVATION STORAGE OUTFLOW	INITIAL 1333.00 240. 0.	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
RATIO OF SAFE	MAXIMUM RESERVOIR ELEV	MAXIMUM DEPTH OVER DAM					
.20	1335.57	0.00	426.	1491.	0.00	45.00	0.00
.30	1336.31	0.00	478.	2239.	0.00	45.00	0.00
.40	1337.05	0.00	530.	2986.	0.00	45.00	0.00
.50	1337.63	.13	570.	3906.	3.00	44.00	0.00
.60	1338.05	.35	605.	4714.	5.00	45.00	0.00
.70	1338.42	.52	671.	5338.	7.00	45.00	0.00
.80	1338.74	.74	613.	6136.	9.00	45.00	0.00
.90	1339.14	.94	627.	6885.	10.00	45.00	0.00
1.00	1339.04	1.14	641.	7634.	11.00	45.00	0.00



\*\*\*\*\*  
FLOOD HYDROGRAPH PACKAGE (REC-1)  
DA - SAFETY VERSION JULY 1976  
LAST MODIFICATION 24 SEP 76  
\*\*\*\*\*

UNIT DATED 03/19/79  
TIME 07:00:00

0.5 PMF with Dam Break Sh 13

NATIONAL DAM INSPECTION PROGRAM  
PENN LAKE DAM  
PMF HYDROGRAPH

JOB SPECIFICATION  
NQ NHW NMIN IDAY IMH IMIN METRC IPLT RT NSTAN  
300 0 10 0 0 0 0 0 -4 0  
JOPER NAT LROPT TRACE  
5 0 0 0

MULTI-PLAN ANALYSES TO BE PERFORMED  
NPLAN= 2 NRTIO= 1 LRTIO= 1

MTIUS= .50

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

\*\*\*\*\*

SUB-AREA RUNOFF COMPUTATION

RUNOFF TO WESEHUYH

ISTAQ ICOMP IECON IIAPE JPLT JPRT INAME ISTAGE IAUTO  
A1 0 0 0 0 0 0 1 0 0

INP26 IUNG TAKEA SNAP THSDA THSPC RATIO ISNOW ISAME LOCAL  
1 1 7.00 0.00 7.00 0.00 0.000 0 1 0

PRECIP DATA  
SPEE PMS P6 H12 W24 R48 R72 R96  
0.00 22.00 111.00 123.00 133.00 142.00 0.00 0.00

THSPC COMPUTED BY THE PROGRAM IS .800

LOSS DATA  
LRJPT STMR DLTKR MTIUL ERAIN STMR RTIOK STRTL CNSTL ALSMX RTIMP  
0 0.00 0.00 1.00 0.00 0.00 1.00 1.00 .05 0.00 0.00

UNIT HYDROGRAPH DATA  
TPE 4.72 CP= .45 NTA= 0

RECESSION DATA  
STMTG= -1.50 UMCST= -.05 RTIOH= 2.00

UNIT HYDROGRAPH END-OF-PERIOD ORIGINATES LAG= 4.71 HOURS CP= .45 VOL= .85  
J. 10. 22. 35. 51. 64. 86. 106. 127. 149.  
171. 194. 218. 243. 268. 293. 315. 337. 356. 374.  
390. 404. 417. 428. 436. 443. 447. 448. 445. 437.  
428. 418. 409. 400. 391. 383. 374. 366. 358. 350.  
342. 335. 327. 320. 313. 306. 299. 293. 286. 280.  
274. 268. 262. 256. 250. 243. 239. 234. 229. 224.  
219. 214. 209. 205. 200. 196. 191. 187. 183. 179.  
175. 171. 167. 164. 160. 157. 153. 150. 146. 143.  
140. 137. 134. 131. 128. 125. 122. 120. 117. 115.  
112. 110. 107. 105. 102. 100. 98. 96. 94. 92.

MO.DA MM.MM PERIOD RAIN EXCS LOSS END-OF-PLAN: FLOW MO.DA HR.MM PERIOD RAIN EXCS LOSS COMP 0

SUM 24.99 22.60 2.39 414437.



# HYDROGRAPH ROUTING

## ROUTING THROUGH PENN LAKE

ISTAU A2	ICOMP	IECON	ITAPE	JPLT	JPRT	INAME	ISTAGE	IAUTO
1	0	0	0	0	0	1	0	0

### ALL PLANS HAVE SAME

#### ROUTING DATA

ULOSS	CLOSS	AVG	INES	ISAMP	IOPT	IPMP	LSTR
0.0	0.00	0.00	1	1	0	0	0
NSIPS	NSTOL	LAG	MASKS	X	TSK	STORA	ISPRAT
1	0	0	0.000	0.000	0.000	-1333.	-1

STAGE	1333.00	1337.50	1340.00	1350.00
FLWA	0.00	3440.00	12000.00	150000.00

CA-CAPACITY	0.	245.	730.	2410.
-------------	----	------	------	-------

ELEVATION	1243.	1333.	1340.	1360.
-----------	-------	-------	-------	-------

CREL	SPWID	COUM	EXPW	FLEVL	COUL	CAREA	EXPL
1333.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0

#### DAM DATA

TOPEL	COUL	EXPD	DAMWID
1337.5	0.0	0.0	0.

#### 044 HRRACH DATA

Z	ELWA	TFAIL	WSEL	FAILEL
2.00	1240.00	1.00	1333.00	1360.00

PEAK OUTFLOW IS 3435. AT TIME 44.50 HOURS

BEGIN DAM FAILURE AT 43.07 HOURS

PEAK OUTFLOW IS 14073. AT TIME 44.25 HOURS

Sh 14


0.5PMF WITH DAM BREAK

0.5PMF with Dam Break  
Sh 15

STATION A2

(\*) POINTS AT NORMAL TIME INTERVAL

(U) INTERPOLATED BEACH HYDROGRAPH  
(H) COMPUTED BEACH HYDROGRAPH



ft

4500  
4400  
4300  
4200  
4100  
4000  
3900  
3800  
3700  
3600  
3500  
3400  
3300  
3200  
3100  
3000  
2900  
2800  
2700  
2600  
2500  
2400  
2300  
2200  
2100  
2000



MEAN FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS  
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)  
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

0.5 PMF with Dam Break  
 Sk 17

RATIOS APPLIED TO FLOWS

OPERATION	STATION	AREA	PLAN RATIO	1
				.50
HYDROGRAPH AT	A1	7.00 ( 18.13)	1	3958.
			( 112.08)	( 3958.)
	2		( 112.08)	( 3958.)
ROUTED TO	A2	7.00 ( 18.13)	1	3935.
			( 111.43)	( 16468.)
	2		( 105.49)	( 16468.)
ROUTED TO	A1	7.00 ( 18.13)	1	3863.
			( 104.38)	( 11152.)
	2		( 1152.)	( 315.80)



# SUMMARY OF DAM SAFETY ANALYSIS

0.5 PMF WITH DAM BREAK  
SH 18

PLAN 1 .....

ELEVATION  
STORAGE  
OUTFLOW

INITIAL VALUE  
1333.00  
246.  
0.

SPILLWAY CREST

TOP OF DAM  
1337.40  
561.  
3440.

RATIO  
OF  
PMF  
.50

MAXIMUM  
DEPTH  
OVER DAM  
.24

MAXIMUM  
STORAGE  
AC-FT  
570.

MAXIMUM  
OUTFLOW  
CFS  
3935.

DURATION  
OVER TOP  
HOURS  
2.83

TIME OF  
MAX OUTFLOW  
HOURS  
44.50

TIME OF  
FAILURE  
HOURS  
0.00

PLAN 2 .....

ELEVATION  
STORAGE  
OUTFLOW

INITIAL VALUE  
1333.00  
246.  
0.

SPILLWAY CREST

TOP OF DAM  
1337.50  
561.  
3440.

RATIO  
OF  
PMF  
.50

MAXIMUM  
DEPTH  
OVER DAM  
.12

MAXIMUM  
STORAGE  
AC-FT  
503.

MAXIMUM  
OUTFLOW  
CFS  
19673.

DURATION  
OVER TOP  
HOURS  
.25

TIME OF  
MAX OUTFLOW  
HOURS  
44.25

TIME OF  
FAILURE  
HOURS  
43.67

PLAN 1 STATION B1

RATIO  
.50

MAXIMUM  
FLOW-CFS  
3861.

MAXIMUM  
STAGE-FT  
1221.0

TIME  
HOURS  
45.00

PLAN 2 STATION B1

RATIO  
.50

MAXIMUM  
FLOW-CFS  
11156.

MAXIMUM  
STAGE-FT  
1223.2

TIME  
HOURS  
44.33

APPENDIX

D

Photographs



*VIEW OF THE RESERVOIR  
FROM THE TOP OF THE DAM*



*DOWNSTREAM FACE OF THE DAM  
SHOWING CUT BRUSH LEFT IN PLACE*



*VIEW FROM THE DOWNSTREAM FACE OF THE DAM  
SHOWING DISCHARGE FROM THE RESERVOIR  
DRAIN PIPE AND SEEPAGE*



*THE GATE VALVE SHELTER. DISCHARGE IS FROM  
THE RESERVOIR DRAIN PIPE AND SEEPAGE*





*APPROXIMATELY 10 C.F.S. DISCHARGE FROM  
RESERVOIR DRAIN PIPE AND SEEPAGE ABOUT  
50 FEET DOWNSTREAM FROM THE DAM*



*DISCOLORED SEEPAGE FLOW IMMEDIATELY  
DOWNSTREAM OF THE DAM*



*CLOSE UP OF THE SEEPAGE FLOW  
IMMEDIATELY DOWNSTREAM OF THE DAM*



*A PORTION OF THE SPILLWAY FLOW  
ABOUT 1000 FEET TO THE LEFT OF THE DAM*

APPENDIX

E

Drawings





O'BRIEN & GERE

SUBJECT

Penn Lake Dam

SHEET

BY

JJ

DATE


4/10/72

JOB NO

## Table of Contents APPENDIX E

Regional Location Map	Plate 1
Plan View of Impoundment	" 2
Dam & Spillway Profiles	" 3
Plan View of Dam Showing Problems	" 4
Cross Sections of Embankment & Spillway	" 5








PLATE 2

**SHEET**

BY


DATE \_\_\_\_\_

**JOB NO**


Penn Lake Dam, G Dam & B. Spillway Profile

2/21/79

PA-00542



PROFILE ALONG CENTERLINE OF TOP OF DAM



PROFILE OF SPILLWAY APPROXIMATELY 1000 FEET LEFT OF THE DAM



SUBJECT

Penn Lake Dam, Plan View of Dam

SHEET


BY

DATE

2/21/79

JOB NO

PA-00452





SUBJECT

Penn Lake Dam, Cross Section, of Emb.

SHEET


BY

DATE

2/22/77

JOB NO

& Spillway



May Seep Along Max. Height of Embankment  $\approx 44'$   
dike toe

1) From "Report upon Three Dams on Wright Creek", 1/29/12

Scale 1" = 40'

TYPICAL SECTION OF DAM



TYPICAL SECTION OF SPILLWAY Scale 1" = 10'

APPENDIX

F

Site Geology

## SITE GEOLOGY

### Penn Lake Dam

Penn Lake is located in a high plateau depression within the glaciated portion of the Appalachian Mountain section of the Valley and Ridge physiographic province. At the site sedimentary units of the predominantly red shales and sandstones of the Mississippian Mauch Chunk formation dip slightly northwest. Some thin deposits of rock debris, remnants of Pleistocene (Wisconsin) glaciation overlie the bedrock formations. No faults or major structural defects are noted in the vicinity of the dam or lake.

